## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,945,829 B2

DATED

: September 20, 2005

INVENTOR(S) : Finzer et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 6,

Lines 23-27, should be replaced with:

-- FIG. 51 is a longitudinal section along line 51-51 of FIG. 51a through the pin housing according to FIG. 49;

FIG 51a is an end view of the pin housing according to FIG. 49;

FIG. 52 is a cross section along line 52-52 of FIG. 52a through the pin housing according to FIG. 49 in which the terminal receiving cavities are viewed from the mating side;

FIG. 52a is a side view of the pin housing according to FIG. 49; --.

Signed and Sealed this

Fourteenth Day of February, 2006

JON W. DUDAS

Director of the United States Patent and Trademark Office